

12/4/2024

Name:

TASK 89951

Date Called in 12/2/2024

Date Scheduled 12/4/2024 9:00 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

					1	100	
Property Address:		885 Willow View Drive					
PID:		2811823440006					
		Owner In	formation				
Name:	David	d & Jodene Marquis					
Mailing Address: (if different from Property)	612-	599-0877					
Phone:	612-327-3972 Email: david.marquis@target.com						
Thomas O 12 OZ 1 OO 12 Zimam Maylatina qui o (Maylatina qui o (Mayla							
		Inspector I	nformation				
Name:	Brian Clark / Joe Cuta						
Company/ Organization		Land Maria	License number:	*** A.J. /			
Phone:			Email:		14		
Inspection							
System	Stand	lard		Wi	Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:	Браста	(= :	,				
				4.			
Toilet Removed	emoved O Yes \(\sqrt{N} \)o						
For Inspection:							
		50/		-	/.	1 m	
Inspectors Signatu				Date:	12-9	-34	
Owners Signature:				Date:			
City Review							
Compliant Corrective Action Required							
Certificate of Com	pliance		Corrective Action Due by:				
Date: Signature: Signature:							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	·

Please no	ote all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.				
Feet	Comment				
Example:	Comment				
0	Chart for All January 1 NE				
1-10	Start for 4" cleanout in NE corner of Basement				
1-10	Misaligned joint –Infiltration				
0	Wye in mechanich Room 4" Sch. 40 PUC				
87'	y" puc wye				
173 Notes:	City Sewer Main				