

Date Called in	1/22/2025
Date Scheduled	

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

RESHOR		v					
Property Address	ss: 3237 Shadywood Cir						
PID: 2011723110045							
		Owner In	nformation				
Name:							
Mailing Address: (if different from Property)							
Phone:			Email:				
		Inspector	Information				
Name:							
Company/ Organization			License number:		2		
Phone:			Email:				
~ .	Inspection					T .11	
System	Standa		should not be connected to the or	nuitam:	Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation	Foundation drains are underground pipes that collect storm water from						
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters						
	basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary						
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:	11/20/2019: 4: pvc sch 40 sewer service anode & tracer wire. will tap main & install new Y on west side of home. Will Inspection new Y when done tapping main. 5lb air test for 15 minutes - all ok 11/25/2019 4" PVC connected to 8" main on west side of home. 32' 6"from mh Anode installed Connected 11/25/2019. Compliancy valid for 10 years from this date.						
Toilet Removed	○ Yes ○ No						
For Inspection:							
Y				TD.			
Inspectors Signature:			Date:				
Owners Signature: Date:							
		City I	Paviany				
City Review Compliant Corrective Action Required							
Compliant Certificate of Compliance Expires: 11/25/2029 Corrective Action Due by:							
Date: Signature: Signature:							
01/22/2025 Name: Kellie Hoen							