

## Date Called in 1/28/2025 Date Scheduled 2/4/2025 10:00 AM

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		1000 Heritage Lane					
PID:		1011723140005					
		Owner Ir	nformation				
Name:	Dennis						
Mailing Address: (if different from Property)				,			
Phone:	952-239	9-5464	Email: dennislibby@rem	nax.net			
11101101			, , ,				
		Inspector	Information				
Name:							
Company/ Organi	zation	۵ .	License number:		0 (14) 0 (20)		
Phone:			Email:				
1 1101101			A BAR CELL		1		
		Inspe	ection	Y			
System	Standa				Pass	Fail	
Roof Drains			should not be connected to the	sanitary	1 1122		
Roof Brains	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation		Foundation drains are underground pipes that collect storm water from					
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)					X	
Notes:	9	0			1		
Toilet Removed For Inspection:	o Yes	<i>\$</i> (No					
	/				211		
1 .1				: 2-4-25			
Owners Signature: Date:							
		City F	Review				
☐ Compliant							
Certificate of Compliance Expires: Corrective Action Due by: 05/04/2025							
Date: Signature: Jank Shirty							
2/10/20	75	Name: Heathe	1) Curio's				

## Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.					
Comment					
Comment					
Start for 4" cleanout in NE corner of Basement					
Misaligned joint –Infiltration					
-Tank at 24 ft -Broken pipe at 16. 7"					
- Broken pipe of 10 1					