

CITY OF ORONO  
INSPECTION NOTICE  
PERMIT NO. SWP23-000062

DATE 8/11/23  
TIME 1:00 PM  
CALLED IN 8/11/23  
SCHEDULED 8/11/23  
COMPLETED 8/15/23

ADDRESS 1800 Shadywood Rd

OWNER \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

CONTRACTOR Bill Coppin

DESCRIPTION Sewer manhole lift

- FOOTING
- POURED WALL
- FOUNDATION DRAIN TILE
- LATHE
- FRAMING
- INSULATION
- FINAL
- AS BUILT - SURVEY
- DEMO - SITE
- DEMO - FINAL
- PLUMBING RI
- PLUMBING FINAL
- MECHANICAL RI
- MECHANICAL FINAL
- WOOD BURNER/FIREPLACE
- WATER HOOK-UP
- SEWER HOOK-UP
- SEPTIC INSTALL
- SEPTIC FINAL
- EXCAV/GRADING/FILLING
- TREE REMOVAL
- SITE INSPECTION
- RATED WALLS
- COMPLAINT
- FOLLOW-UP
- FOUNDATION/REMOVAL

OWNER/CONTRACTOR TO MEET YOU:  YES  NO

COMMENTS: Found manhole on North side of driveway of 1810 Shadywood. This manhole has 1800+1810 sewer services inside, manhole is raised to driveway height.

All ok

- WORK SATISFACTORY: PROCEED
- CORRECT WORK & PROCEED
- CORRECT WORK, CALL FOR REINSPECTION BEFORE COVERING
- CORRECT UNSAFE CONDITION WITHIN \_\_\_\_\_ HOURS. INSPECTOR WILL RETURN
- STOP ORDER POSTED. CALL INSPECTOR
- INSPECTION REQUIRED. CALL TO ARRANGE ACCESS.
- PROJECT COMPLETE
- ISSUE CERTIFICATE OF OCCUPANCY \_\_\_\_\_ TEMPORARY \_\_\_\_\_ PERMANENT
- PHOTO TAKEN
- CITATION ISSUED

Call for the next inspection 24 hours in advance. (952) 249-4600

Owner/Contractor on site: Bill

Inspector: Scott

CODE REQUIREMENTS ARE FOR YOUR PERSONAL HEALTH AND SAFETY!