

Date Called in Date Scheduled 2/20/25 @ 1:30pm

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	2285 Webber Hills Road
PID:	0311723330003

2205 Webber 111115 Road							
PID:		0311723330003					
	Owner Information						
Name:	Dennis & Karen Pederson						
Mailing Address: (if different from Property)							
Phone:	952-	-334-1514	Email:	Dennis_pederso	on@mac	.com	
		Inspector In	nformation				
Name:							
Company/ Organization		**	License number:		1		
Phone:	,	· · · · ·	Email:				
		X 8 1 2					
		Inspe	ction	414 (1)		the state of	
System	Stand					Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation Drains	around pumped to the s	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.					
Sump Pumps	baseme system	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					/
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:							
Toilet Removed	o Yes	o No	3				
For Inspection:	1.						
Inspectors Signatu		funtar Gille				2-20	- 25
Owners Signature: Date:							

Inspectors Signature: Auntau Gille	Date: 2-20-25
Owners Signature:	Date:
9	

City Review				
★ Compliant				☐ Corrective Action Required
Certificate of Compliance E	xpires: 2	20/	35	Corrective Action Due by:
Date:	Signature	: '		Beatty suces
Date: 2-20- 25	Name:		F	feather Smilig

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.		
Feet	Comment	
Example:		
0	Start for 4" cleanout in NE corner of Basement	
1-10	Misaligned joint –Infiltration	
0	-115' was as far as we could push carnera into the line.	
	Camera into the line.	
_		
Matan		
Notes:		
-		