

TASK # 94731

Date Called in
Date Scheduled 5-9-29

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	1926 Fagerness Point Road
PID:	1711723230016

		Owner Information	1	**************************************
Name:	David Thorp - Realto	or		
Mailing Address:				
(if different from				
Property)				
Phone:	952-356-5855	Email:	Dave@davethorp.com	

	Inspector I	nformation	ia
Name:			
Company/ Organization	City of Orono	License number:	
	Highview Plumbing		
Phone:	952-249-4686 612-916-1685	Email:	

	Inspection	•	
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	\'V	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	/	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.		
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	The state of the s	L
Notes:	Mineral deposits in Several Spots upor review - Jimmy Helson, Supervisor	N	
Toilet Removed For Inspection:	∘ Yes ∘ No		

Inspectors Signature:	Date: 5 - 9-25
Owners Signature:	Date:

		City	Review	e	
11 Compliant				n Required	
Certificate of Compliance B	xpires:		Corrective Action Due by	y: 8-9-	2025
Date: Class	Signature:	[gent	the Sonies		
2/7/45	Name:	Heath	er Smilia		

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Feet	Comment
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration
0	ISTACK FLOW 4" STACK C.O. WADEN STATES.
11,	FINAL C.O.
17	y"ABS of y" Puc
29	milesi Dogosit
ust .	rest we?
41'	MINERAL DODOST TEST WYE? H'POR > 4"CAST"
Si [*]	MENERAL DEPOSITE MINERAL DEPOSIT 45° KT WYE?? WHYE AT MAIN WADER WITTER
70'	MINERAL DEPOSIT
71	45° KT WYE??
22	whe AT MAIN WADER WITTER
76	LOCATED IN MATER 11 Deep
Notes:	