

## Task #95126 THE SDAY Date Called in City Of Orono Date Scheduled Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	4108 Highwood Road
PID:	0711723440089

	(	Owner Information	1	
Name:	Denise & Matthew W	affensmith		
Mailing Address: (if different from Property)				
Phone:	952-486-2889	Email:	dwaffensmith@gmail.com	

Inspector Information			
Name:			
Company/ Organization	City of Orono Highview Plumbing	License number:	
Phone:	952-249-4686   612-916-1685	Email:	

	Inspection		
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	X	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	K	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.		
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	K.	
Notes:			
Toilet Removed For Inspection:	• Yes • No		

/_ /	h-	6-4-2025
Inspectors Signature: 72		Date: 6-3-25
Owners Signature:		Date:

1	City	Review	
🕅 Compliant		Corrective Action Required	r
Certificate of Compliance E	xpires: 6-3-35	Corrective Action Due by:	
Date: U	Signature:	Geatty Smight	
6-9-25	Name: H	cather Smileig	

## Service Line Inspection Details

ť

•

ì

۰,

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Scrvice Pipe	

This report must include a digital copy o Comment Start for 4" cleanout in NE corner of Basement Misaligned joint -Infiltration ENTER AND RUSTACK C.O. CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC			
Misaligned joint -Infiltration ENTER ALL RUSTACK 2.0. ELOUG '	Tw	CIAL ACIE	
$C \in \mathcal{O}(\mathbb{R}^{d})^{d}$	T	CIALACIC	
4ª east			
и 			
4" CLAY			
6" PEAST De		•	
MAIN			
·			
	4" CLAY 6" PEAST DE MAIN	4" CLAY 6" PLAST DE MATA	41 east 41 clay 61 feast de MATA

.

¢